

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

671  
NNE  
1/2-1  
0.971 mi.  
5128 ft.

PRIVATE HOME  
412 LAKE STREET  
BROOKLYN, NY

NY LTANKS S107410751  
N/A

Relative:  
Higher

Actual:  
15 ft.

LTANKS:

Name: PRIVATE HOME  
Address: 412 LAKE STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0507703 / 2005-11-30  
Facility ID: 0507703  
Site ID: 353166  
Spill Date: 2005-09-27  
Spill Cause: Tank Failure  
Spill Source: Private Dwelling  
Spill Class: Not reported  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: JMKRIMGO  
Referred To: Not reported  
Reported to Dept: 2005-09-27  
CID: 444  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: True  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-09-27  
Spill Record Last Update: 2005-11-30  
Spiller Name: NICHOLAS  
Spiller Company: PRIVATE HOME  
Spiller Address: 408 LAKE STREET  
Spiller County: 001  
Spiller Contact: YUSUPOV TESHUCO  
Spiller Phone: (718) 449-4340  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 300464  
DEC Memo: "09/28/05. J.Krimgold visit the site. Heating oil smell in the basement on 412 Lake St. Oil stain on the sinder-block wall adjacent to 408 Lake St. Inspected 408 Lake St. 275 gal HO tank in the basement located in the tank room adjacent to 412 Lake St. Owner Nicholas admitted that the tank let go about 6 month ago and some oil went toward the adjacent wall and some puddled on the floor. The tank was patched and speedy dry is still on the floor. RP was ordered to complete the cleanup power-wash floor and walls, and seal the sinderblock wall with epoxy paint on both sides. CSL letter was given to the RP at the site. 09/29/05. Nicholas (RP) called and informed that his contractor should come over to his place Saturday or Monday to complete the job. JK. 09/29/05. Bob from EnviroSpect (631-366-5294)called and informed that they were hired to do the job. Anticipated completion on Monday. 10/07/05. Nicholas called and informed that all works have been completed and they are ready for inspection. J.Krimgold informed him that no further action is required at this time."

Remarks:

"TANK LEAKED IN BASEMENT: UNKNOWN FURTHER DETAILS"

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID:	353166
Operable Unit ID:	1110632
Operable Unit:	01
Material ID:	2100670
Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported